

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Robert L. Morgan

Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY www.nr.utah.gov

April 15, 2003

TO:

Minerals File

FROM:

Doug Jensen, Senior Reclamation Engineer

RE:

Site Inspection, Thirstystone Resources, Inc, Picture Stone #1 & #2, S/053/028,

Washington County, Utah

Date of Inspection:

April 2, 2003

Time of Inspection:

12:30 p.m.

Conditions:

Warm, Windy

Participants:

Wayne Hedberg, Doug Jensen, DOGM

Purpose of Inspection:

While in the area, the site was visited to familiarize myself with the site and conditions.

Getting to the site:

The site is located ~ ½ mile northeast of Harrisburg, east of the Harrisburg access road.

Observations:

The site was inactive at the time of the visit. The site did not present any environmental concerns. The total disturbance at the site was well within the required <5 acre limit for a small mine permit.

There was a small dump area and the pad of the quarry was covered with larger rocks that were numbered and apparently awaiting shipment. The overall site was well managed and material derived from the mining activity has been kept within a small area of disturbance.

Pictures of the site were taken and are included in this report.

Conclusions and Recommendations:

This site has been inactive for several years, but as noted above, this inactivity does not present any concerns at this time.

jb
O:\M053-Washington\S0530028-PictureSpring\Final\04022003ins.doc
CC. BL m
Operator

T. 1 .

Utan! Where ideas connect





